

SPECIFICATIONS OF CITRIC ACID 50% LIQUID

Parameters	Limits
Appearance	Clear Solution
Assay as Citric Acid	48 to 52%
Iron	10 ppm max.
Heavy Metals	5 ppm max
Specific Gravity	1.23 to 1.26

Citric acid is used as an acidulant, as iron control agent, and as a chelant.

Packing: 550 lb drums, 2750 lb totes, 330 ga totes, bulk tank-trucks

Availability: Houston, TX (Beasley, TX); Midland, TX